

Important

Improper fixing of the pressure vessel


Below: Incorrect fitting using Mastic Sealant, this may lead to extensive flooding!



Mastic sealant failed



led to damaged vessel



Water leaks



Please check your vessel is attached with a bracket.

Please check your pressure vessel is fitted to the wall with a **secure bracket.**

If your boiler has mastic sealant, contact **Higgins** or your Landlord immediately!

Higgins Contact:
Michael Owen

Tel: 07786275402 **Email:** Michael.owen@higginsconstruction.co.uk

Church Street (Maidstone) Management Company Limited
Cantium Lodge, Terrace Road, Maidstone, ME16 8HU

Website: www.theoldhospitalmaidstone.co.uk
Email: office@theoldhospitalmaidstone.co.uk
Company Number: 06545435